



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

March 4, 1985

CERTIFIED RETURN RECEIPT REQUESTED  
(P 402 457 110)

Mr. Charles H. Gent, Jr.  
Genwal Coal Company, Inc.  
P. O. Box 1201  
Huntington, Utah 84538

Dear Mr. Gent:

RE: Emergency Spillway Modification, Genwal Coal Company,  
Inc., Crandall Canyon Mine, ACT/015/032, #2, #3 and #4,  
Emery County, Utah

On September 10, 1984, the Division issued approval of the plans and installation details for the proposed emergency spillway from the sediment pond to Crandall Creek. This approval was contingent upon concurrence of the U. S. Forest Service (USFS) prior to construction.


On February 20, 1985, the USFS informed Genwal that that agency does not concur with the design and installation details for this structure as currently proposed. The USFS identified specific details as lacking, which include: (1) overlapping of belting on traverse and longitudinal seams; (2) type of mechanical connection to maintain channel integrity; and (3) dimensions, type of metal, gauge of material and effectiveness of velocity dissipator. Therefore, the Division requests that Genwal submit this additional information immediately in order that the USFS may review and approve the emergency spillway and construction as soon as possible.

Please submit 14 copies of this information to the Division for review and distribution to the pertinent state and federal agencies. Should you have any questions, contact the Division at your earliest possible convenience.

Page 2  
Mr. Charles H. Gent, Jr.  
ACT/015/032  
March 4, 1985

Thank you for your cooperation in this matter.

Sincerely,

  
D. Wayne Hedberg  
Permit Supervisor/  
Reclamation Hydrologist

MMB/btb  
cc: William H. Boley  
Allen Klein  
Ron Naten  
Steve McNeal  
Ron Daniels  
Dave Lof  
Tom Munson  
Rick Smith  
Tom Suchoski  
8813R-50 & 51